Serial Port 4 initialized suc<u>cessfully</u> Waiting for input signal..... Received Gamma Calibration start signal. 25 characters received from Pu600-->PU600: Calibrate Complete 25 characters received from Pu900-->PU900: Cal<u>ibrate Complete</u> 25 characters received from Pu300-->PU300: Calibrate Complete Waiting for input signal..... Received Background start signal. 29 characters received from Symmetry-->Symmetry: Ba<u>ckground Complete</u> 26 characters received from Pu600-->PU600: Background Complete 4 characters received from N<u>MC-->PASS</u> 26 characters received from Pu900-->PU900: Background Complete 26 characters received from Pu300-->PU300: Background Complete

Received Measure Control start signal. 4 characters received from NMC-->PASS Waiting for input signal....

Waiting for input signal.....

Serial Port 3 initialized suc<u>cessfully</u>